www.harrispaints.com f / harrispaints TDS 2018.01



Duratone Premium Semi-gloss Acrylic Latex

Basic Uses: interior/exterior surfaces



TECHNICAL DATA

VISCOSITY: 105-110 Ku's FLASH POINT: Non-Flammable SOLIDS (WEIGHT): 37% SOLIDS (VOLUME): 25%

DRY FILM THICKNESS: Recommended film thickness 4.0 mils wet and 1.4 mils dry.

SIZES

1 gallon (3.785 Liters) 5 gallon (18.925 Liters)

FINISH

Semi gloss (50%@ 60°)

COLOR

White Light Bone-White Bases: Pastel, tint, deep and accent to be used with HARRIS® COLOR SYSTEM

DESCRIPTION

A premium quality latex semi-gloss paint for new or previously painted interior or exterior. It is easy to apply and dries quickly to produce a washable finish of super durability and color retention. This paint contains a mildewcide designed to inhibit the growth of mildew on the dry paint film itself.

COMPOSITION AND PROPERTIES: A semi-gloss finish based on a copolymer of vinyl and acrylic monomers. Excellent gloss retention and resistance to blistering.

SURFACES PREPARATION

NEW SURFACES PREPARATION: Remove dirt, dust and loose particles. Wash and Rinse all surfaces to remove oil, grease and other foreign substances using an industrial cleaner. Rinse completely and let dry.

Concrete, stucco, and structural block prime with this paint. Wood: countersink nail heads. Caulk nail heads and joints or cracks with latex type caulk. Shellac all knots and sap streaks. Sand rough areas and wipe clean. Prime entire surface with this paint.

PREVIOUSLY PAINTED SURFACES: Can be used over either oil (previously sanded) or latex painted surfaces. Either surface must be clean to obtain proper

adhesion.

SURFACES IN GOOD CONDITION: Sand any glossy areas and dust clean. Wipe away dirt and chalk. Clean and spot prime any failed areas. Use soap and water on overhead areas such as eaves and ceilings to remove invisible residues, a major cause of peeling in these areas. Rinse clean and allow drying. Prime with this paint.

SURFACES IN POOR CONDITION: Remove heavy chalk by scrubbing with soap and water. Wash under eaves at same time. Rinse clean and allow drying. Prime the complete area as recommended under new surfaces.

METHOD OF APPLICATION: Stir thoroughly before and during application. Use a brush 3/8" (9.5 mm) nap roller. Two coats are recommended on all surfaces for best results and full gloss development. On sound, repainted surfaces, one (1) coat may be sufficient.

COVERAGE: 300 - 500 sq. ft. (27 - 46 sq. m.) per gallon, depending on surface texture and porosity.

DRYING (NORMAL CONDITIONS): To touch in one (1) hour; to recoat in tree (3) hours. These periods will be extended on cool or humid days.

CLEANUP: Use warm, soapy water immediately.

PRECAUTION

KEEP FROM FREEZING! Do not apply when surface or air temperature is below 50° (10° C). Stop painting at least two (2) hours before you expect heavy dew or the temperature to drop below 50° F (10° C).

CAUTION: Do not take internally. In case of eye contact, flush thoroughly with water. Do not rub eye. In case skin contact, flush area immediately with clean water. Use only with adequate ventilation. Close container after each use. KEEP OUT OF THE REACH OF CHILDREN.