www.harrispaints.com f / harrispaints



Rain Buster Elastomeric Roof Primer

Basic Uses: Exterior concrete and wood surfaces

OOF SEALERS



TDS 2018.01

TECHNICAL DATA

VISCOSITY: 55-60 KU'S (KREBS-STORMER) WEIGHT/GALLON: 8.34 ± 0.10 lbs. FLASH POINT: Non-flammable DRY FILM THICKNESS: Recommended film thickness: 16 mils wet and 8 mils dry.

SIZES

5 gallons

FINISH

Satin @ Geometry 60°

COLOR

White

DESCRIPTION

Is a penetrating, milky white liquid for application over roof and wall surfaces, such as concrete, brick, wood, and others. It is a waterproofing primer coating formulated with a 100% Acrylic Emulsion Polymer. It features the ability to penetrate deeply into the pores and cracks, forming an elastic, impermeable transparent film in addition to the excellent adhesion property.

APPLICATION

SURFACE PREPARATION:

Surfaces must be dried and free of oil, grease, dirt, and loose concrete. Remove all foreign, old matter and loose coatings by sandblasting, with high pressure water blasting (3,000 p.s.i.) or wire brushing. Ideally, all water pounding should be corrected before applying the primer. Prime the entire surface to be sealed with this Roof Coating Primer; allow 30 minutes to 1 hour drying time to recoat with HARRIS® Rain Buster Roof Sealer.

MILDEWED SURFACES:

Surfaces that have been coated with tar or any other kind of sealer should be inspected and those sections of tar or sealer that have cracked or have come loose should be removed. Then follow procedures as for new surfaces.

METHOD OF APPLICATION:

Use brush, roller or soft broom. It can also be sprayed. Apply two coats allowing two (2) hours drying time between coats. Apply second coat crossing direction of application of first application.

THINNING:

Not normally recommended, but if necessary, add water up to 1/2 pint per gallon. Do not mix with solvent or solvent thinned paints.

COVERAGE:

300-400 sq. ft. per gallon, depending on surface texture and porosity on the first coat and 100-120 sq. ft. on the second coat.

WHEN TO APPLY:

Select a warm, sunny day and consult your weather bureau to make sure there is no forecast of rain. Do not apply after 4:00 pm. overnight for recoating.

CLEANUP:

Clean brushes and equipment thoroughly in warm water and detergent.

PRECAUTIONS

Do not apply if temperature of air or surface is below 50°F (10°C). Stop painting at least two (2) hours before you expect dew to form, rain or the temperature to drop.

CAUTION! Combustible. HARMFUL IF INHALED

Keep away from heat and open flame. Avoid prolonged contact with skin and breathing of vapor or spray mist. Close container after each use. Use with adequate ventilation.

Do not take internally.

KEEP OUT OF THE REACH OF CHILDREN.